

OF 15 THE RESPONSELTY ON TO SATE & REE COMMENCEMENT OD NOT SCHE D PAWNINGS DAVINGS IMAY NOT BE US COMPRISHING IMAY NOT BE US COMPRISH RESPRED COMPRISH RESPRED COMPRISH REPORTING F, THE LESIGNERG CONDENT COMPRISH NOTICE - CO DESIGNERT CONDENT OF C THE CHARGE NOTICE - CO DESIGNERT CONDENT OF C DESCAMENT - USE OF THE SHALL NDENNEY & SAVE LEGA FEES) DAMAGES, ON ARSING BY RESSON OF CA	ALL CONTRACTORS MUST COMPLY WITH ALL CODES & BYLAWS HWING JURISDICTION IT IS THE RESPONSIBILITY OF THE APPROPRIATE CONTRACTOR TO CHECK & VERIFY ALL DIMENSIONS ON SITE & REPORT ALL ERRORS AND/OR OMISSIONS TO THE DESIGNEP PRIOR TO		REVISIONS		PROJECT	SCALE 3/32" = 1'-0"
			REVISIONS			DRAWN BY CB
		NO.	NO. ITEM		UGANDA HIGH COMMISSION	DATE AUG. 8, 2022
	- COPYRIGHT RESERVED - THIS DRAWING & DRAWINGS CONTAINED HEREIN ARE THE EXCLUSIVE PROPERTY OF JIM BELL DESIGN & SHALL NOT BE USED OR REPRODUCED WITHOUT	11	ISSUED FOR B.P.	02/17/22		CHKED BY JB
	COPYRGHT NOTICE - COPYRIGHT IN THIS ELECTRONIC DOCUMENT BELONGS TO JIM BELL DESIGN. THIS ELECTRONIC DOCUMENT MAY NOT BE FORWARDED TO OTHERS, TRANSMITTED, DOWINLOADED OR REPRODUCED IN ANY FORMATIK WIETHER PRINT OR ELECTRONIC WITHOUT	12	COORDINATION	02/21/22	CLIENT	APPRD BY JB
		13	CONSTRUCTION SET	ET 05/8/22		PROJECT NO. 219-35
					STITTSVILLE, ONTARIO	SHEET NO.
					DRAWING	
						A.1
					SITE PLAN	/ * • •

Tree Information Report

Prepared by Colleen Eames, Arborist. Arborist Consulting Ottawa arboristconsultingottawa@gmail.com 613-884-3394

Tree Owner	Ugandan High Commission
Address of Tree(s)	235 Mariposa Ave, Ottawa
Location of Tree(s) on property	Various around property
Species of Tree(s)	Various, see descriptions
Date of tree Inspection	April 16, 2021
Reason for Removal	N/A trees to be maintained – except where recommended below.
Reason for Inspection	Application for Minor Variance, Heritage plan in place. Renovations to be done on building and landscaping.
Restrictions	No Butternut present.

Tree Descriptions:

There are various clusters and individual trees around the property. Trees are to be maintained during the renovation and as such a Tree Protection Plan is recommended to protect the trees and their root systems. Trees are marked as individuals or clusters in red on the attached site plan and pictures. Some sizes are approximate due to access restrictions. Red lines indicate the approximate location for tree protective fences, the distance given is from the largest tree in the cluster.

Tree	Tree Location	Species	Size	Description
1	Centre of front	Apple	58cm	Large apple in fair condition, some dieback
	yard			in the middle.
2	Right side of	Ironwood	38cm	Good condition. Very close to existing
	front yard (E)			driveway which is to be removed during
				renovation.
3	Right side of	White birch	22cm	Multi-stemmed tree, may be on
	front yard (E)			neighbouring property. Fair condition.
				Some overhang on existing driveway which
				may need pruned.
4	Right side of	Japanese	17cm	Multi-stemmed, may be on neighbouring
	front yard (E)	lilac		property. Good condition.
5	Along left side of	ironwoods	18cm	Mix of trees running along left side fence,
	front yard (W)	and yellow		trees are all 18cm or less, fair condition,
		birches		some crowding.

6	Along left side fence in back yard (WNW) Back left corner	Mix of maples Maples and	30cm 25cm	Cluster of mixed trees, mostly maple along left side of back yard (west side), largest tree is 30cm, also 28cm, 27cm and 26cm maples, most other trees are under 15cm. good condition. Cluster of trees in back left corner of (NW
/	(NW)	Japanese lilac	23011	side) property, maples 19, 22 and 25cm. Maples in good condition, Japanese lilac in fair condition.
8	Neighbouring tree (N)	Maple	~20cm	Neighbouring tree in property to the back, behind existing shed (North side). Multi- stemmed tree with largest stem approximately 20cm, in good condition.
9	Back yard, back- right side (NE)	Cluster of maples	24cm	Cluster of Maples in back yard to right side of yard (North East). largest tree is 24cm, also 20cm, 20cm and a dozen trees under 15cm. In good condition.
10	Neighbouring tree (NE)	Chestnut	~60cm	Neighbouring tree in back right corner (NE side). could not access, however this is a large tree and should be noted in case work comes within Critical Root Zone.
11	Neighbouring tree (NE)	Elm	~55cm	Neighbouring tree in back right corner (NE side). could not access, however this is a large tree and should be noted in case work comes within Critical Root Zone.
12	Back yard to right hand side of house (E)	Cluster of maples	24cm	Cluster of maples and mixed trees to right hand side of house (East side). Some trees growing into chain-link fence and crowding with each other and with the building. Some of these trees may need removed.

Arborist Recommendations.

To Preserve the trees a Tree Protection Plan should be put in place with the following measures:

- A temporary fence 1.2 high should be erected along the Critical Root Zone (CRZ) of each tree or cluster, at a distance of 10X the listed DBH. Approximate fence locations are drawn on the accompanying site plan in red.
- Any roots > 1" in diameter that are encountered while digging should be cut cleanly with a sharp, clean saw.
- Adequate water should be given to any impacted trees during the summer to mitigate the loss of water uptake by the loss of part of its root system. No fertilizer should be applied to the trees.
- Care should be taken not to harm any other part of the trees, including trunk and branches.

- Grading of land around the trees should be avoided.
- Driving of vehicles or storage of heavy materials should be avoided in the CRZ of the trees.
- Tree 2, the ironwood in the front yard is very close to the existing curved driveway, which is to be removed. This will need to be done in the close vicinity of the tree and well within the CRZ. Care should be taken when removing the driveway not to dig any deeper than necessary and to limit the driving or storing of vehicles or materials in the remaining CRZ are of this tree. When re-grading the area under the tree it is important not to change the grade level or to bury the roots.
- Tree 3, the white birch next to the driveway may require some clearance pruning to allow for vehicles to pass without hitting and ripping the branch. This should be done by a qualified arborist and pruning limited to clearance purposes only.

Colleen Eames, Arborist

4pr. 20, 21

Date

Contractor

Date

Owner of Property

Date









