



## Tree Information Report v4.0

Submitted as part of Committee of Adjustment Application to the City of Ottawa

**Address:** 290 Holmwood  
**Date of Report:** July 31, 2024  
**Date of Site Visit:** November 3, 2022, November 29, 2023 and April 16, 2024  
**Prepared by:** Astrid Nielsen, RPF, ISA Certified Arborist®; [astrid.nielsen@dendronforestry.ca](mailto:astrid.nielsen@dendronforestry.ca)  
**Client:** Allan Bateman, [prestwick24@gmail.com](mailto:prestwick24@gmail.com)

**This Report must be read in its entirety, including the Assumptions and Limiting Conditions.**

### Purpose of the Report

The purpose of this report is to provide the client with a detailed description of all protected trees on site as per the City of Ottawa's Tree Protection By-law No. 2020-340. This report is part of a Committee of Adjustment application to the City of Ottawa and considers the impact that the proposed development will have on the trees. The assessment of the suitability of tree retention is based on the information provided at the time of report preparation which includes:

- Topographic survey prepared by Stantec dated August 5, 2022
- Concept Plan prepared by Hobin Architects, dated July, 2024

*Update for version 4.0: This version includes the development of the western lot only. The eastern lot will be developed at a later date.*

This assessment does not consider additional factors that could influence tree retainability such as:

- site grading
- installation of services for the new units
- capping of existing water and sewer services
- installation of gas lines for the new units
- site access

*The potential for retaining those tree(s) identified for retention in this report may change as more information on the site-specific construction details is provided during the building permitting phase.*

For those trees that are recommended for retention, mitigation measures are provided to reduce the impact during construction. It should be noted that the construction phase includes all site works that could impact trees, from the capping of services at the beginning to the final landscaping steps at the end. While a rationale for removing trees may be provided based on document review, **this report does not grant permission to remove trees: a permit from the city must be received before removal of distinctive trees can occur.**



**Methodology**

The following materials/tools were reviewed as part of this report:

- Site Plan
- GeoOttawa tree inventory layer and aerial photography
- Google© Street View imagery – various years

A site visit was conducted to collect the following information from each tree classified as protected under the City of Ottawa’s Tree Protection By-law No. 2020-340:

- Diameter at breast height (1.3 m from grade)
- Species
- Tree health
- Relevant measurements such as distance to the existing structures like fences, driveways, etc

**Tree Information**

The following is an inventory of all trees on the site and adjacent City property. It also includes Distinctive Trees (private trees with a diameter at breast height (dbh) of 30 cm or greater) on adjacent properties whose Critical Root Zone (CRZ) extend into the subject area. The CRZ is an area around the trunk with a radius equivalent to 10 times the diameter of the trunk. This does not take into account infrastructure such as buildings and asphalt and assumes the tree has no restrictions on root growth.

Tree <sup>1</sup>	Species	Diameter at breast height (cm)	Ownership <sup>2,3</sup>	Condition	Action	Arborist Recommendations
1	Colorado spruce ( <i>Picea pungens</i> )	57	Private	Good	Remove	Remove based on conflict with proposed home; <b>Tree Permit from city required for removal</b>
2	Colorado spruce ( <i>Picea pungens</i> )	56	Private	Good	Remove	Remove based on conflict with proposed home; <b>Tree Permit from city required for removal</b>
3	Colorado spruce ( <i>Picea pungens</i> )	45	Private	Good	Remove	Remove based on conflict with proposed home; <b>Tree Permit from city required for removal</b>
4	Colorado spruce ( <i>Picea pungens</i> )	49	Private	Good	Remove	Remove based on conflict with proposed home; <b>Tree Permit from city required for removal</b>
5	Norway maple ( <i>Acer platanoides</i> )	35	Private	Good; slight lean downhill	Retain	Retain and protect; recommend retaining grading in this area, if possible
6	Colorado spruce ( <i>Picea pungens</i> )	28	Private	Fair; thin crown	Retain	Retain and protect; recommend retaining grading in this area, if possible
7	Norway maple ( <i>Acer platanoides</i> )	32	Private	Good; 2 codominant stems	Retain	Retain and protect; recommend retaining grading in this area, if possible
8	Norway maple ( <i>Acer platanoides</i> )	28	Private	Good; some pruning by hydro for clearance	Retain	Retain and protect; recommend retaining grading in this area, if possible



9	Manitoba maple ( <i>Acer negundo</i> )	28	Private	Fair; cavity with decay at 2 m above grade, 2 m scar on upper side of tree	Remove	Remove based on poor health; <b>no permit required for removal</b>
10	Norway maple ( <i>Acer platanoides</i> )	18	Private	Fair/poor; topped by hydro	Remove	Remove based on poor health; <b>no permit required for removal</b>
11	Manitoba maple ( <i>Acer negundo</i> )	29.2	Private	Good	Retain	Retain and protect; recommend retaining grading in this area, if possible
12	Norway maple ( <i>Acer platanoides</i> )	27	Private	Good	Retain	Retain and protect; recommend retaining grading in this area, if possible
13	Norway maple ( <i>Acer platanoides</i> )	26	Private	Good/fair; leaning over adjacent property to rear	Retain	Retain and protect; recommend retaining grading in this area, if possible
14	Norway maple ( <i>Acer platanoides</i> )	24	Private	Good	Retain	Retain and protect; recommend retaining grading in this area, if possible
15	Norway maple ( <i>Acer platanoides</i> )	14	Private	Good	Retain	Retain and protect; recommend retaining grading in this area, if possible
16	Silver maple ( <i>Acer saccharinum</i> )	80 (estimate)	Adjacent property at 53 Findlay	Good	Retain	Retain and protect; recommend retaining grading in this area, if possible
17	Norway spruce ( <i>Picea abies</i> )	35	Private	Good	Retain	Retain and protect
18	Norway spruce ( <i>Picea abies</i> )	33	Jointly owned with 296 Holmwood	Good	Retain	Retain and protect
19	Norway spruce ( <i>Picea abies</i> )	46	Private	Good	Remove	Retain and protect
20	Norway spruce ( <i>Picea abies</i> )	32	Private	Good, slight lean towards adjacent property	Remove	Retain and protect
21	Norway spruce ( <i>Picea abies</i> )	16	Private	Good	Retain	Retain and protect
22	Norway spruce ( <i>Picea abies</i> )	33	Private	Good	Retain	Retain and protect

<sup>1</sup> Please refer to the attached Tree Information map for tree numbers. Note that this includes a tree layer added to the site plan (in pdf format) provided by the client. This layer includes only information about the trees and the original site plan is not altered in this process.

<sup>2</sup>Ownership of the tree in this report is based on the information provided and should not be used as a determination of ownership. For ownership disputes, a survey should be relied on. For boundary trees, consent from the adjacent property owner is required for removal as part of the application.



<sup>3</sup>Trees on adjacent properties do not include a full assessment. The diameters are estimated, and the health is estimated based on what is visible from the subject property. Trees along the property line may also have limited health assessments if part of the tree is not visible.

### Proposed Development and Conservation

The property is heavily treed, and there is a significant grade change from the back to the front of the property. Many of the trees are located on the steep slope, especially the spruce trees along the east side. Since the first phase of development includes only the western lot, the spruce trees, 17-22 along the east side, will be retained at this time. They should be protected as indicated in the map during the demolition of the existing home.

The large line of trees along the rear of the property consists mostly of Norway maple (invasive species) and Manitoba maple (naturalized species). These are located on top of a retaining wall at a higher grade than the existing home. Provided the retaining wall can be retained and the grading does not change in this section, most of these trees could be retained. However, given their location uphill from four new homes as well as restricted rooting space, keeping them properly maintained, including regular pruning and inspection by a certified arborist, will be important in keeping the risk of failure low. Two trees (9 and 10) have been identified for removal and replacement due to poor health. Both are under 30 cm, and therefore not protected under the by-law and no permit is required for removal.

Tree no. 5 is located below the retaining wall, and there may be conflicts with the new grades. Every opportunity for safe retention of this tree will be explored with the engineering team in the next phases of the project.

Prior to any site works, protective fencing should be installed around the trees in the rear as indicated in the attached Tree Information Map and maintained until all construction on site has been completed as per the **City of Ottawa Tree Protection Specifications (March 2021)**. Within the fenced area, the following tree protection guidelines should be applied:

- Do not change the grade
- Do not store construction material
- Do not operate machinery
- Do not convert to hard surface or change the landscaping
- Do not excavate unless it is a method that has been pre-approved by the City
- Do not place signs, notices or posters to any tree
- Do not damage the root system, trunk, or branches of any tree
- Direct the exhaust away from the tree

The tree protection fencing must be 1.2 m in height and constructed of a rigid or framed material (e.g. modulus – steel, plywood hoarding, or snow fence on a 2”X4” wood frame) with posts 2.4 m apart such that the fence location cannot be altered. All supports must be placed outside of the CRZ and installation must minimize damage to existing roots.

If the fenced tree protection area must be reduced to facilitate construction, *one* of the following mitigation measures should be applied:



- Place a layer of 6-12 inches (15 to 30 cm) of woodchip mulch to the area
- Apply ¾ (2 cm) inch plywood, or road mats over a 4+ inch (10 cm) thick layer of the wood chip mulch
- Apply 4-6 inches (10 to 15 cm) of gravel over a taut, staked, geotextile fabric

### **Proposed Tree Planting**

A Tree Planting Plan has been prepared by Dendron Forestry Services that shows 6 new trees on the site including 3 trees in the front right of way, 2 in the rear yard, and one on the adjacent property at 286 Holmwood. More specific details on the location and species of trees can be established once construction has been completed.

The undersigned personally inspected the property and issues associated with this report on November 3, 2022 and November 29, 2023. On Behalf of Dendron Forestry Services,



Astrid Nielsen, MFC, RPF (Registered Professional Forester)  
ISA Certified Arborist®, ON-1976  
ISA Tree Risk Assessment Qualified  
Principal, Dendron Forestry Services  
[Astrid.nielsen@dendronforestry.ca](mailto:Astrid.nielsen@dendronforestry.ca)  
(613) 805-9663 (WOOD)



*Figure 1: Photo taken from rear of property, Colorado spruce along the west property line, trees 1-4*



*Figure 2: Side view of trees along the rear property line*



*Figure 3: Trees along the rear property line*





*Figure 4: Spruce trees along the eastern property line, trees 17-22. Note the limited rooting space and steep slope.*



## ASSUMPTIONS AND LIMITING CONDITIONS

### Intended Use of the Report

This Report was prepared by Dendron Forestry Services (hereafter “Dendron”) at the request of the Client. The results, observations, interpretations, analysis, recommendations, and conclusions contained within this Report are to be used solely for the purposes outlined within this Report. All other uses are impermissible and unintended, unless specifically stated in writing in the Report.

### Intended User of the Report

This Report was prepared by Dendron for the exclusive use of the Client and may not be used or relied upon by any other party. All other users are unintended and unauthorized, unless specifically stated in writing in the Report.

### Limitations of this Report

This Report is based on the circumstances and on-site conditions as they existed at the time of the site inspection and the information provided by the Client and/or third parties to Dendron. On-site conditions may limit the extent of the on-site inspection(s) conducted by Dendron, including weather events such as rain, flooding, storms, winds, tornados, snowfall, snow cover, hail; obstructions including fencing, dwellings, buildings, sheds, plants, and animals; lack of access to the entire perimeter of the tree due to adjacent properties; the shape of the tree; and accessibility of the tree crown, branches, trunk, or roots for examination.

In the event that information provided by the Client or any third parties, including but not limited to documents, records, site and grading plans, permits, or representations or any site conditions are updated or change following the completion of this Report, this Report is no longer current and valid and cannot be relied upon for the purpose for which it was prepared. Dendron and its agents, assessors, and/or employees are not liable for any damages, injuries, or losses arising from amendments, revisions, or changes to the documents, records, site and grading plans, permits, representations, or other information upon which Dendron relied in preparing this Report.

No assessment of any other trees or plants has been undertaken by Dendron. Dendron and its agents, assessors, and/or employees are not liable for any other trees or plants on or around the subject Property except those expressly identified herein. The results, observations, interpretations, analysis, recommendations, and conclusions contained within this Report apply only to the trees identified herein.

Trees and plants are living organisms and subject to change, damage, and disease, and the results, observations, interpretations, analysis, recommendations, and conclusions as set out in this Report are valid only as at the date any inspections, observations, tests, and analysis took place. No guarantee, warranty, representation, or opinion is offered or made by Dendron as to the length of the validity of the results, observations, interpretations, analysis, recommendations, and conclusions contained within this Report. As a result the Client shall only rely upon this Report as representing the results, observations, interpretations, analysis, recommendations, and conclusions that were made as at the date of such inspections, observations, tests, and analysis. The trees discussed in this Report should be re-assessed periodically and at least within one year of the date of this Report.

### No Opinion regarding ownership of the Tree

This Report was not prepared to make a determination as to ownership of the subject tree(s). Where ownership of the subject tree(s) is identified within this Report, said identification is based on the information provided by the Client and third parties, including surveys, permits, and site and grading plans and may not be relied upon as a guarantee, warranty, or representation of ownership.

### Assumptions

This Report is based on the circumstances and conditions as they existed at the time of the site inspection and the information provided by the Client and/or third parties to Dendron. Where documents, records, site and grading plans, permits, representations, and any other information was provided to Dendron for the purpose of preparing this Report, Dendron assumed that said information was correct and up-to-date and prepared this Report in reliance on that information. Dendron and its agents, assessors, and/or employees, are not responsible for the veracity or accuracy of such information. Dendron and its agents, assessors, or employees are not liable for any damages, injuries, or losses arising from inaccuracies, errors, and/or omissions in the documents, records, site and grading plans, permits, representations, or other information upon which Dendron relied in preparing this Report.

For the purpose of preparing this Report, Dendron and its agents, assessors, and/or employees assumed that the property which is the subject of this Report is in full compliance with all applicable federal, provincial, municipal, and local statutes, regulations, by-laws, guidelines, and other related laws. Dendron and its agents, assessors, and/or employees are not liable for any issues with respect to non-compliance with any of the above-referenced statutes, regulations, bylaws, guidelines, and laws as it may pertain to or affect the property to which this Report applies.

For the purpose of preparing this Report, Dendron and its agents, assessors, and/or employee assumed that there are no hidden or unapparent conditions affecting the results, observations, interpretations, analysis, recommendations, and conclusions contained within this Report.

### No Publication

The Client acknowledges and agrees that all intellectual property rights and title, including without limitation, all copyright in this Report shall remain solely with Dendron Forestry. Possession of this Report, or a copy thereof, does not entitle the Client or any third party to the right of publication or reproduction of the Report for any purpose save and except where Dendron has given its prior written consent.

Neither all nor any part of the contents of this Report shall be disseminated to the public through advertising, public relations, news, sales, the internet or other media (including, without limitation, television, radio, print or electronic media) without the prior written consent of Dendron Forestry.



### **Implementing the Report Recommendations**

Dendron and its agents, assessors, and/or employees accept no responsibility for the implementation of any part of this Report unless specifically requested to provide oversight on the implementation of the recommendations. In the event that inspection or supervision of all or part of the implementation of the within recommendations is requested, that request shall be in writing and the details agreed to in writing by both parties.

Dendron and its agents, assessors, and/or employees are not liable for any damages or injuries arising from the manner in which the recommendations in this Report are implemented, including failure to, incorrect, or negligent implementation of the recommendations.

### **Further Services**

Neither Dendron nor any assessor employed or retained by Dendron for the purpose of preparing or assisting in the preparation of this Report shall be required to provide any further consultation or services to the Client, save and except as already carried out in the preparation of this Report and including, without limitation, to act as an expert witness or witness in any court in any jurisdiction unless the Client has first made specific arrangements with respect to such further services, including, without limitation, providing the payment of the Report's regular hourly billing fees.

### **Limits of Liability**

In carrying out this Report, Dendron and its agents, assessors, and/or employees have exercised a reasonable standard of care, skill, and diligence as would be customarily and normally provided in carrying out this Report. While reasonable efforts have been made to ensure that the trees recommended for retention are healthy, no guarantees are offered, or implied, that these trees, or all parts of them will remain standing. It is professionally impossible to predict with absolute certainty the behaviour of any single tree or group of trees, or all their component parts, in all given circumstances. Inevitably, a standing tree will always pose some risk. Most trees have the potential to fall, lean, or otherwise pose a danger to property and persons in the event of adverse weather conditions, and this risk can only be eliminated if the tree is removed.

Without limiting the foregoing, no liability is assumed by Dendron for:

- a) any legal description provided with respect to the Property;
- b) issues of title and or ownership respect to the Property;
- c) the accuracy of the Property line locations or boundaries with respect to the Property; and
- d) the accuracy of any other information provided to Dendron by the Client or third parties;
- e) any consequential loss, injury or damages suffered by the Client or any third parties, including but not limited to replacement costs, loss of use, earnings and business interruption; and
- f) the unauthorized distribution of the Report.

The total monetary amount of all claims or causes of action the Client may have as against Dendron Forestry, including but not limited to claims for negligence, negligent misrepresentation, and breach of contract, shall be strictly limited solely to the total amount of fees paid by the Client to Dendron Forestry pursuant to the Contract for Services dated November 16, 2022, for which this Assessment was carried out.

Further, under no circumstance may any claims be initiated or commenced by the Client against Dendron or any of its directors, officers, employees, contractors, agents, assessors, or Assessors, in contract or in tort, more than 12 months after the date of this Report.

### **No Third Party Liability**

This Report was prepared by Dendron exclusively for the Client for the purpose set out in the Report. Any use which a third party makes of this Report, or any reliance on or decisions a third party may make based upon this Report, are made at the sole risk of any such third parties. Dendron Forestry accepts no responsibility for any damages or loss suffered by any third party or by the Client as a result of decisions made or actions based upon the unauthorized use or reliance of this Report by any such party.

### **General**

Any plans and/or illustrations in this Report are included only to help the Client visualize the issues in this Report and shall not be relied upon for any other purpose. This report is best viewed in colour. Any copies printed in black and white may make some details difficult to properly understand. Dendron accepts no liability for misunderstandings due to a black and white copy of the report.

Notwithstanding any of the above, nothing in this Report is taken to absolve the Client of the responsibility of obtaining a new Report in the event that the circumstances of the tree change.




TIR Map – 290 Holmwood Avenue  
 Tree layer prepared by  
 Dendron Forestry Services  
 Version 4.0, July 31, 2024  
 For more information, please contact: info@dendronforestry.ca

**Note:** the tree layer has been added to the original site plan supplied by the client in pdf format. This layer refers to the trees only, and the original plan has not been altered in the process. Refer to the original plan for details as quality is lost when importing the plan into the mapping software used to create the tree layer.

- TREE PROTECTION REQUIREMENTS:**
- PRIOR TO ANY WORK ACTIVITY WITHIN THE CRITICAL ROOT ZONE (CRZ = 10 X DIAMETER) OF A TREE, TREE PROTECTION FENCING MUST BE INSTALLED SURROUNDING THE CRITICAL ROOT ZONE, AND REMAIN IN PLACE UNTIL THE WORK IS COMPLETE.
  - UNLESS PLANS ARE APPROVED BY CITY FORESTRY STAFF, FOR WORK WITHIN THE CRZ:
    - DO NOT PLACE ANY MATERIAL OR EQUIPMENT - INCLUDING OUTHOUSES;
    - DO NOT ATTACH ANY SIGNS, NOTICES OR POSTERS TO ANY TREE;
    - DO NOT RAISE OR LOWER THE EXISTING GRADE;
    - TUNNEL OR BORE WHEN DIGGING;
    - DO NOT DAMAGE THE ROOT SYSTEM, TRUNK, OR BRANCHES OR ANY TREE;
    - ENSURE THAT EXHAUST FUMES FROM ALL EQUIPMENT ARE NOT DIRECTED TOWARD ANY TREE CANOPY.
    - DO NOT EXTEND HARD SURFACE OR SIGNIFICANTLY CHANGE LANDSCAPING.
  - TREE PROTECTION FENCING MUST BE AT LEAST 1.2M IN HEIGHT, AND CONSTRUCTED OF RIGID OR FRAMED MATERIALS (E.G. MODULOC - STEEL, PLYWOOD HOARDING, OR SNOW FENCE ON A 2"x4" WOOD FRAME) WITH POSTS 2.4M APART, SUCH THAT THE FENCE LOCATION CANNOT BE ALTERED. ALL SUPPORTS AND BRACING MUST BE PLACED OUTSIDE OF THE CRZ, AND INSTALLATION MUST MINIMISE DAMAGE TO EXISTING ROOTS. (SEE DETAIL)
  - THE LOCATION OF THE TREE PROTECTION FENCING MUST BE DETERMINED BY AN ARBORIST AND DETAILED ON ANY ASSOCIATED PLANS FOR THE SITE (E.G. TREE CONSERVATION REPORT, TREE INFORMATION REPORT, ETC). THE PLAN AND CONSTRUCTED FENCING MUST BE APPROVED BY CITY FORESTRY STAFF PRIOR TO THE COMMENCEMENT OF WORK.
  - IF THE FENCED TREE PROTECTION AREA MUST BE REDUCED TO FACILITATE CONSTRUCTION, MITIGATION MEASURES MUST BE PRESCRIBED BY AN ARBORIST AND APPROVED BY CITY FORESTRY STAFF. THESE MAY INCLUDE THE PLACEMENT OF PLYWOOD, WOOD CHIPS, OR STEEL PLATING OVER THE ROOTS FOR PROTECTION OR THE PROPER PRUNING AND CARE OF ROOTS WHERE ENCOUNTERED.
- THE CITY'S TREE PROTECTION BY-LAW, 2020-340 PROTECTS BOTH CITY-OWNED TREES, CITY-WIDE, AND PRIVATELY-OWNED TREES WITHIN THE URBAN AREA. PLEASE REFER TO WWW.OTTAWA.CA/TREEBYLAW FOR MORE INFORMATION ON HOW THE TREE BY-LAW APPLIES.

**Failure to install and maintain fencing as described in this report may result in fines from the city.**



**Legend**

- Critical Root Zone
- Tree to be removed
- Tree Protection Area
- Private Tree
- Tree either fully or partly on adjacent property

Tree #	Species	Diameter at breast height (cm)	Action	Arborist Recommendations
1	Colorado spruce ( <i>Picea pungens</i> )	57	Remove	Remove based on conflict with proposed home; <b>Tree Permit from city required for removal</b>
2	Colorado spruce ( <i>Picea pungens</i> )	56	Remove	Remove based on conflict with proposed home; <b>Tree Permit from city required for removal</b>
3	Colorado spruce ( <i>Picea pungens</i> )	45	Remove	Remove based on conflict with proposed home; <b>Tree Permit from city required for removal</b>
4	Colorado spruce ( <i>Picea pungens</i> )	49	Remove	Remove based on conflict with proposed home; <b>Tree Permit from city required for removal</b>
5	Norway maple ( <i>Acer platanoides</i> )	35	Retain	Retain and protect; recommend retaining grading in this area, if possible
6	Colorado spruce ( <i>Picea pungens</i> )	28	Retain	Retain and protect; recommend retaining grading in this area, if possible
7	Norway maple ( <i>Acer platanoides</i> )	32	Retain	Retain and protect; recommend retaining grading in this area, if possible
8	Norway maple ( <i>Acer platanoides</i> )	28	Retain	Retain and protect; recommend retaining grading in this area, if possible
9	Manitoba maple ( <i>Acer negundo</i> )	28	Remove	Remove based on poor health; <b>no permit required for removal</b>
10	Norway maple ( <i>Acer platanoides</i> )	18	Remove	Remove based on poor health; <b>no permit required for removal</b>
11	Manitoba maple ( <i>Acer negundo</i> )	29.2	Retain	Retain and protect; recommend retaining grading in this area, if possible
12	Norway maple ( <i>Acer platanoides</i> )	27	Retain	Retain and protect; recommend retaining grading in this area, if possible
13	Norway maple ( <i>Acer platanoides</i> )	26	Retain	Retain and protect; recommend retaining grading in this area, if possible
14	Norway maple ( <i>Acer platanoides</i> )	24	Retain	Retain and protect; recommend retaining grading in this area, if possible
15	Norway maple ( <i>Acer platanoides</i> )	14	Retain	Retain and protect; recommend retaining grading in this area, if possible
16	Silver maple ( <i>Acer saccharinum</i> )	80 (estimate)	Retain	Retain and protect; recommend retaining grading in this area, if possible
17	Norway spruce ( <i>Picea abies</i> )	35	Retain	Retain and protect
18	Norway spruce ( <i>Picea abies</i> )	33	Retain	Retain and protect
19	Norway spruce ( <i>Picea abies</i> )	46	Remove	Retain and protect
20	Norway spruce ( <i>Picea abies</i> )	32	Remove	Retain and protect
21	Norway spruce ( <i>Picea abies</i> )	16	Retain	Retain and protect
22	Norway spruce ( <i>Picea abies</i> )	33	Retain	Retain and protect

