# **Tree Information Report v2.0**

Submitted as part of Building Permit Application to the City of Ottawa

**Date of Report:** April 16, 2024

**Property Address:** 1598 Prince of Wales Drive

Prepared for: Roca Homes c/o Roberto Campagna; roberto@rocahomes.ca

**Prepared by:** Kevin Myers, ISA Certified Arborist®; <a href="mailto:kevin.myers@dendronforestry.ca">kevin.myers@dendronforestry.ca</a>

**Date of Site Visit:** February 21, 2024

This Report must be read in its entirety, including the Assumptions and Limiting Conditions.

# **Purpose of the Report**

The purpose of this report is to provide the client with a detailed description of all protected trees on site as per the City of Ottawa's Tree Protection By-law No. 2020-340. This report is part of a building permit application to the City of Ottawa and considers the impact that the proposed development will have on the trees. Technical and design documents provided by the client are reviewed as part of this report, and conclusions are made on the suitability for retaining the protected trees on the site. For those trees that are recommended for retention, mitigation measures are provided to reduce the impact during construction.

*Update for version 2.0*: After consultation with the city, the client has provided a new site plan. This report updates the first version, dated February 26, 2024 taking the new site plan into account. Recommendations have changed as a result of this change.

While a rationale for removing trees may be provided based on document review and the site visit, this report does not grant permission to remove trees: a permit from the city must be received before removal of distinctive trees can occur.

## Methodology

The following materials were reviewed as part of this report:

- Proposed grading and servicing plan by TL Mak Engineering Consultants, dated January 2024
- Site Plan, received April 16, 2024
- Survey by Stantec Geomatics Ltd., dated June 7, 2021
- GeoOttawa tree inventory layer and aerial photography
- Google© Street View imagery various years

A site visit was conducted to collect the following information from each tree classified as protected under the City of Ottawa's Tree Protection By-law No. 2020-340:

- Diameter at breast height (1.3 m from grade)
- Species
- Tree health

**Committee of Adjustment** 

Received | Reçu le **2024-08-07** 

City of Ottawa | Ville d'Ottawa

Comité de dérogation

### **Existing site conditions**

The site is currently occupied by a single building with a large rear yard. There is a short hedge, approximately 4 feet tall, running along the south property line which has been pruned recently. It is expected the majority of this hedge is on the adjacent property and most stems are below 10cm DBH. On all other boundaries of the property are large numbers of unmaintained shrubs and trees. Species noted include: common buckthorn (*Rhamnus cathartica*) and glossy buckthorn (*Frangula alnus*) – both invasive species in Ontario; Manitoba maples (*Acer negundo*); common lilac (*Syringa vulgaris*); white birch (*Betula papyrifera*); white oak (*Quercus alba*); and white ash (*Fraxinus americana*).

Around Trees 10 and 11 there is a clump of lilac (*S. vulgaris*). This clump falls on city property, and consists of over 20 stems below 10cm.

Appendix A is an inventory of all trees that are protected under City of Ottawa Tree Protection (By-law No. 2020-340) on the site and adjacent City property. This includes Distinctive Trees (private trees with a diameter at breast height (dbh) of 30 cm or greater) and city-owned trees of all sizes. It also includes Distinctive Trees on adjacent properties whose Critical Root Zone (CRZ) extend into the subject area. The CRZ is an area around the trunk with a radius equivalent to 10 times the diameter of the trunk. This does not take into account infrastructure such as buildings and asphalt and assumes the tree has no restrictions on root growth.

## **Proposed development and Tree protection**

With the level of activity and densification on this site, tree preservation will be very difficult.

**Tree 1** can be preserved for future canopy on site – care is to be taken not to tear roots when removing the existing driveway – if any roots are torn the damaged portions are to be cleanly cut off by hand at the nearest union. Fencing should be installed as shown in the map and described below.

**Tree 3** is far enough on the adjacent property that stability will not be a concern – to protect its rooting space, fencing is to be installed at the rear of the property as indicated in the map and described below.

**Tree 7** is a multi-stemmed Manitoba maple (*Acer negundo*) – most of which is growing and leaning away from the subject property. This tree sits on the south side of an existing drainage ditch that runs along the southern property boundary. It is expected that this tree will be able to endure construction. While it is unclear how many roots may have developed past the drainage ditch, protective fencing should be erected as shown in the map to protect the CRZ on the subject site.

**Tree 10 and 11** are self-seeded Norway maples (*Acer platanoides*), which is an invasive species in Ontario. They are growing under wires, near a sidewalk, and are already leaning to find light from among the lilac bushes – these trees have very poor future growth conditions. It is recommended these trees be removed and replanted.



#### Tree Protection

**Prior to any site works**, protective fencing should be installed around the Tree Protection Area as indicated in the attached Tree Information Map and maintained until all construction on site has been completed as per the City of Ottawa Tree Protection Specifications (March 2021).

Failure to install and maintain fencing as shown on the attached map may result in fines from the city.

Within the fenced area, the following tree protection guidelines should be applied:

- Do not change the grade
- Do not store construction material
- Do not operate machinery
- Do not convert to hard surface or change the landscaping
- Do not excavate unless it is a method that has been pre-approved by the City
- Do not place signs, notices or posters to any tree
- Do not damage the root system, trunk, or branches of any tree
- Direct the exhaust away from the tree

The tree protection fencing must be 1.2 m in height and constructed of a rigid or framed material (e.g. modulus – steel, plywood hoarding, or snow fence on a 2"X4" wood frame) with posts 2.4 m apart such that the fence location cannot be altered. All supports must be placed outside of the CRZ and installation must minimize damage to existing roots.

If the fenced tree protection area must be reduced to facilitate construction, *one* of the following mitigation measures should be applied:

- Place a layer of 6-12 inches (15 to 30 cm) of woodchip mulch to the area
- Apply ¾ (2 cm) inch plywood, or road mats over a 4+ inch (10 cm) thick layer of the wood chip mulch
- Apply 4-6 inches (10 to 15 cm) of gravel over a taut, staked, geotextile fabric

The undersigned personally inspected the property and issues associated with this report on February 21, 2024. On Behalf of Dendron Forestry Services,

Kevin Myers, MFC

ISA Certified Arborist®, ON-2907A

kevin.myers@dendronforestry.ca

(514) 726-8531



# **APPENDIX A**

# TREE INFORMATION TABLE

Tree <sup>1</sup>	Species	DBH (cm)	Ownership <sup>2</sup>	Tree Condition	Approximate distance to excavation (m)	Action	Forester recommendation
1	White spruce ( <i>Picea</i> glauca)	16	City	Fair/Good: pruned around wires – asymmetrical crown	Driveway: 6	Retain	Retain and protect as per the City of Ottawa Tree Protection specifications (March 2021).
2	White birch ( <u>Betula</u> <u>papyrifera</u>	38, 23	Subject property	Fair/Poor: decay in large stem – small stem leaning; shorter-lived species nearing pinnacle of growth	House: 2.5	Remove	Remove due to health status and level of activity on site. <b>Tree</b> permit required for removal.
<b>3</b> <sup>4</sup>	Willow (Salix spp.)	100 (estimate)	Adjacent – 1589 Senio	Fair: large wound with decay	Garage: 5.5	Retain	Retain – no action required
44	Red maple (Acer rubrum)	20, 20, 46, 15	Subject property	Good	Parking area: 5	Retain	Retain and protect as per the City of Ottawa Tree Protection specifications (March 2021).
54	Red maple (Acer rubrum)	35	Subject property	Good: slight lean to the North	Parking area: 5	Retain	Retain and protect as per the City of Ottawa Tree Protection specifications (March 2021).
6	White spruce ( <i>Picea</i> glauca)	36	Subject property	Fair/Poor: lean to East (approx. 10°); approx. 40% defoliation	0	Remove	Remove: in building footprint.  Tree permit required for removal.
74	Manitoba maple ( <i>Acer</i> negundo)	24, 52, 30	Adjacent – 1590 Prince of Wales	Fair: spreading form; dead branch with decay; epicormic shoots throughout canopy; small pockets of decay	House: 3	Retain	Retain and protect as per the City of Ottawa Tree Protection Specifications (March 2021).
8	Colorado spruce ( <i>Picea</i> pungens)	53	Subject property	Fair/Good: lean corrected through growth; approx. 15% defoliation	0	Remove	Remove: in excavation footprint.  Tree permit required for removal.
9	Manitoba maple ( <i>Acer</i> negundo)	64	Subject property	Poor: significant decay at the middle of the trunk and at base; lean to the	0	Remove	Remove due to health status.  Tree permit required for removal.



# **Dendron Forestry Services**

				Northwest; dead branches in canopy			
<b>10</b> <sup>4</sup>	Norway maple (Acer platanoides)	10	City	Fair: growing under wires; lean to west	Driveway: 5.5	Remove	Remove due to undesirable species and level of activity on site. Tree permit required for removal.
114	Norway maple (Acer platanoides)	14	City	Fair: asymmetrical crown due to pruning around wires; moderate lean to the east	Driveway: 6	Remove	Remove due to undesirable species and level of activity on site. Tree permit required for removal.

<sup>1</sup> Please refer to the attached Tree Information map for tree numbers. Note that this includes a tree layer added to the grading plan (in pdf format) provided by the client. This layer includes only information about the trees and the original grading plan is not altered in this process.

<sup>&</sup>lt;sup>2</sup>Ownership of the tree in this report is based on the information provided and should not be used as a determination of ownership. For ownership disputes, a survey should be relied on. For boundary trees, consent from the adjacent property owner is required for removal as part of the application.

<sup>&</sup>lt;sup>3</sup>Trees on adjacent properties do not include a full assessment. The diameters are estimated, and the health is estimated based on what is visible from the subject property. Trees along the property line may also have limited health assessments if part of the tree is not visible.

<sup>&</sup>lt;sup>4</sup>The location of these trees was not provided and has been estimated

# **APPENDIX B**

# **PHOTOGRAPHS**



Tree 1 (right) - city spruce to be retained, and Tree 2 (left) - private birch to be removed.



Trees along the rear property line. Tree 3 (left) - adjacent willow to be retained. Trees 4 and 5 (right) - private red maples to be removed.





Above: Trees along the south property line - largely unmaintained and in poor condition.

Right: Tree 6 – private spruce to be removed.

Left: Tree 8 – private spruce to be removed.







Canopy of Tree 7.

Base of Tree 7.









Clockwise from above: Tree 9 - private Manitoba maple in poor condition to be removed.

Base of Tree 9 with decay in the small cavity.

Decay on the stem of Tree 9.





## **APPENDIX C**

#### **ASSUMPTIONS AND LIMITING CONDITIONS**

#### Intended Use of the Report

This Report was prepared by Dendron Forestry Services (hereafter "Dendron") at the request of the Client. The results, observations, interpretations, analysis, recommendations, and conclusions contained within this Report are to be used solely for the purposes outlined within this Report. All other uses are impermissible and unintended, unless specifically stated in writing in the Report.

#### Intended User of the Report

This Report was prepared by Dendron for the exclusive use of the Client and may not be used or relied upon by any other party. All other users are unintended and unauthorized, unless specifically stated in writing in the Report.

#### **Limitations of this Report**

This Report is based on the circumstances and on-site conditions as they existed at the time of the site inspection and the information provided by the Client and/or third parties to Dendron. On-site conditions may limit the extent of the on-site inspection(s) conducted by Dendron, including weather events such as rain, flooding, storms, winds, tornados, snowfall, snow cover, hail; obstructions including fencing, dwellings, buildings, sheds, plants, and animals; lack of access to the entire perimeter of the tree due to adjacent properties; the shape of the tree; and accessibility of the tree crown, branches, trunk, or roots for examination.

In the event that information provided by the Client or any third parties, including but not limited to documents, records, site and grading plans, permits, or representations or any site conditions are updated or change following the completion of this Report, this Report is no longer current and valid and cannot be relied upon for the purpose for which it was prepared. Dendron and its agents, assessors, and/or employees are not liable for any damages, injuries, or losses arising from amendments, revisions, or changes to the documents, records, site and grading plans, permits, representations, or other information upon which Dendron relied in preparing this Report.

No assessment of any other trees or plants has been undertaken by Dendron. Dendron and its agents, assessors, and/or employees are not liable for any other trees or plants on or around the subject Property except those expressly identified herein. The results, observations, interpretations, analysis, recommendations, and conclusions contained within this Report apply only to the trees identified herein.

Trees and plants are living organisms and subject to change, damage, and disease, and the results, observations, interpretations, analysis, recommendations, and conclusions as set out in this Report are valid only as at the date any inspections, observations, tests, and analysis took place. No guarantee, warranty, representation, or opinion is offered or made by Dendron as to the length of the validity of the results, observations, interpretations, analysis, recommendations, and conclusions contained within this Report. As a result the Client shall only rely upon this Report as representing the results, observations, interpretations, analysis, recommendations, and conclusions that were made as at the date of such inspections, observations, tests, and analysis. The trees discussed in this Report should be re-assessed periodically and at least within one year of the date of this Report.

#### No Opinion regarding ownership of the Tree

This Report was not prepared to make a determination as to ownership of the subject tree(s). Where ownership of the subject tree(s) is identified within this Report, said identification is based on the information provided by the Client and third parties, including surveys, permits, and site and grading plans and may not be relied upon as a guarantee, warranty, or representation of ownership.

#### Assumptions

This Report is based on the circumstances and conditions as they existed at the time of the site inspection and the information provided by the Client and/or third parties to Dendron. Where documents, records, site and grading plans, permits, representations, and any other information was provided to Dendron for the purpose of preparing this Report, Dendron assumed that said information was correct and up-to-date and prepared this Report in reliance on that information. Dendron and its agents, assessors, and/or employees, are not responsible for the veracity or accuracy of such information. Dendron and its agents, assessors, or employees are not liable for any damages, injuries, or losses arising from inaccuracies, errors, and/or omissions in the documents, records, site and grading plans, permits, representations, or other information upon which Dendron relied in preparing this Report.

For the purpose of preparing this Report, Dendron and its agents, assessors, and/or employees assumed that the property which is the subject of this Report is in full compliance with all applicable federal, provincial, municipal, and local statutes, regulations, by-laws, guidelines, and other related laws. Dendron and its agents, assessors, and/or employees are not liable for any issues with respect to non-compliance with any of the above-referenced statutes, regulations, bylaws, guidelines, and laws as it may pertain to or affect the property to which this Report applies.

For the purpose of preparing this Report, Dendron and its agents, assessors, and/or employee assumed that there are no hidden or unapparent conditions affecting the results, observations, interpretations, analysis, recommendations, and conclusions contained within this Report.

#### No Publication



The Client acknowledges and agrees that all intellectual property rights and title, including without limitation, all copyright in this Report shall remain solely with Dendron Forestry. Possession of this Report, or a copy thereof, does not entitle the Client or any third party to the right of publication or reproduction of the Report for any purpose save and except where Dendron has given its prior written consent.

Neither all nor any part of the contents of this Report shall be disseminated to the public through advertising, public relations, news, sales, the internet or other media (including, without limitation, television, radio, print or electronic media) without the prior written consent of Dendron Forestry.

#### **Implementing the Report Recommendations**

Dendron and its agents, assessors, and/or employees accept no responsibility for the implementation of any part of this Report unless specifically requested to provide oversight on the implementation of the recommendations. In the event that inspection or supervision of all or part of the implementation of the within recommendations is requested, that request shall be in writing and the details agreed to in writing by both parties.

Dendron and its agents, assessors, and/or employees are not liable for any damages or injuries arising from the manner in which the recommendations in this Report are implemented, including failure to, incorrect, or negligent implementation of the recommendations.

#### **Further Services**

Neither Dendron nor any assessor employed or retained by Dendron for the purpose of preparing or assisting in the preparation of this Report shall be required to provide any further consultation or services to the Client, save and except as already carried out in the preparation of this Report and including, without limitation, to act as an expert witness or witness in any court in any jurisdiction unless the Client has first made specific arrangements with respect to such further services, including, without limitation, providing the payment of the Report's regular hourly billing fees.

#### **Limits of Liability**

In carrying out this Report, Dendron and its agents, assessors, and/or employees have exercised a reasonable standard of care, skill, and diligence as would be customarily and normally provided in carrying out this Report. While reasonable efforts have been made to ensure that the trees recommended for retention are healthy, no guarantees are offered, or implied, that these trees, or all parts of them will remain standing. It is professionally impossible to predict with absolute certainty the behaviour of any single tree or group of trees, or all their component parts, in all given circumstances. Inevitably, a standing tree will always pose some risk. Most trees have the potential to fall, lean, or otherwise pose a danger to property and persons in the event of adverse weather conditions, and this risk can only be eliminated if the tree is removed.

Without limiting the foregoing, no liability is assumed by Dendron for:

- a) any legal description provided with respect to the Property;
- b) issues of title and or ownership respect to the Property;
- c) the accuracy of the Property line locations or boundaries with respect to the Property; and
- d) the accuracy of any other information provided to Dendron by the Client or third parties;
- e) any consequential loss, injury or damages suffered by the Client or any third parties, including but not limited to replacement costs, loss of use, earnings and business interruption; and
- f) the unauthorized distribution of the Report.

The total monetary amount of all claims or causes of action the Client may have as against Dendron Forestry, including but not limited to claims for negligence, negligent misrepresentation, and breach of contract, shall be strictly limited solely to the total amount of fees paid by the Client to Dendron Forestry pursuant to the Contract for Services dated February 15, 2024, for which this Assessment was carried out.

Further, under no circumstance may any claims be initiated or commenced by the Client against Dendron or any of its directors, officers, employees, contractors, agents, assessors, or Assessors, in contract or in tort, more than 12 months after the date of this Report.

#### **No Third Party Liability**


This Report was prepared by Dendron exclusively for the Client for the purpose set out in the Report. Any use which a third party makes of this Report, or any reliance on or decisions a third party may make based upon this Report, are made at the sole risk of any such third parties. Dendron Forestry accepts no responsibility for any damages or loss suffered by any third party or by the Client as a result of decisions made or actions based upon the unauthorized use or reliance of this Report by any such party.

#### General

Any plans and/or illustrations in this Report are included only to help the Client visualize the issues in this Report and shall not be relied upon for any other purpose. This report is best viewed in colour. Any copies printed in black and white may make some details difficult to properly understand. Dendron accepts no liability for misunderstandings due to a black and white copy of the report.

Notwithstanding any of the above, nothing in this Report is taken to absolve the Client of the responsibility of obtaining a new Report in the event that the circumstances of the tree change.

Tree <sup>1</sup>	Species	DBH (cm)	Tree Condition	Forester recommendation
1	White spruce ( <i>Picea</i> glauca)	16	Fair/Good: pruned around wires – asymmetrical crown	Retain and protect as per the City of Ottawa Tree Protection specifications (March 2021).
2	White birch ( <u>Betula</u> <u>papyrifera</u>	38, 23	Fair/Poor: decay in large stem – small stem leaning; shorter-lived species nearing pinnacle of growth	Remove due to health status and level of activity on site. Tree permit required for removal.
3 <sup>4</sup>	Willow (Salix spp.)	100 (estimate)	Fair: large wound with decay	Retain – no action required
44	Red maple (Acer rubrum)	20, 20, 46, 15	Good	Retain and protect as per the City of Ottawa Tree Protection specifications (March 2021).
<b>5</b> <sup>4</sup>	Red maple ( <i>Acer rubrum</i> )	35	Good: slight lean to the North	Retain and protect as per the City of Ottawa Tree Protection specifications (March 2021).
6	White spruce ( <i>Picea</i> glauca)	36	Fair/Poor: lean to East (approx. 10°); approx. 40% defoliation	Remove: in building footprint. <b>Tree</b> permit required for removal.
<b>7</b> <sup>4</sup>	Manitoba maple ( <i>Acer</i> negundo)	24, 52, 30	Fair: spreading form; dead branch with decay; epicormic shoots throughout canopy; small pockets of decay	Retain and protect as per the City of Ottawa Tree Protection Specifications (March 2021).
8	Colorado spruce ( <i>Picea</i> pungens)	53	Fair/Good: lean corrected through growth; approx. 15% defoliation	Remove: in excavation footprint. <b>Tree</b> permit required for removal.
9	Manitoba maple ( <i>Acer</i> negundo)	64	Poor: significant decay at the middle of the trunk and at base; lean to the Northwest; dead branches in canopy	Remove due to health status. Tree permit required for removal.
<b>10</b> <sup>4</sup>	Norway maple (Acer platanoides)	10	Fair: growing under wires; lean to west	Remove due to undesirable species and level of activity on site. <b>Tree</b> permit required for removal.
<b>11</b> <sup>4</sup>	Norway maple (Acer platanoides)	14	Fair: asymmetrical crown due to pruning around wires; moderate lean to the east	Remove due to undesirable species and level of activity on site. <b>Tree</b> permit required for removal.






Note: the tree layer has been added to the original base layer supplied by the client in pdf format. This layer refers to the trees only, and the original base has not been altered in the process, although it may be cropped. Refer to the original plan for details as quality is lost when importing the plan into the software used to create the tree layer.

Base Layer: Site plan by S.A.I Consulting, received April 16, 2024

# TIR Map – 1598 Prince of Wales Drive

		7
Date	Revision	Prepared By
06/02/2024	Version 1	KM
16/04/2024	New Site plan	KM



# Failure to install and maintain fencing as described in this report may result in fines from the city.

TREE PROTECTION REQUIREMENTS:


- PRIOR TO ANY WORK ACTIVITY WITHIN THE CRITICAL ROOT ZONE (CRZ = 10 X DIAMETER) OF A TREE, TREE PROTECTION FENCING MUST BE INSTALLED SURROUNDING THE CRITICAL ROOT ZONE, AND REMAIN IN PLACE UNTIL THE WORK IS COMPLETE.
- 2. UNLESS PLANS ARE APPROVED BY CITY FORESTRY STAFF, FOR WORK WITHIN THE CRZ:
- DO NOT PLACE ANY MATERIAL OR EQUIPMENT INCLUDING OUTHOUSES;
- DO NOT ATTACH ANY SIGNS, NOTICES OR POSTERS TO ANY TREE;
- DO NOT RAISE OR LOWER THE EXISTING GRADE; - TUNNEL OR BORE WHEN DIGGING;
- DO NOT DAMAGE THE ROOT SYSTEM, TRUNK, OR BRANCHES OR ANY
- ENSURE THAT EXHAUST FUMES FROM ALL EQUIPMENT ARE NOT
- DIRECTED TOWARD ANY TREE CANOPY. - DO NOT EXTEND HARD SURFACE OR SIGNIFICANTLY CHANGE
- LANDSCAPING
- 3. TREE PROTECTION FENCING MUST BE AT LEAST 1.2M IN HEIGHT, AND CONSTRUCTED OF RIGID OR FRAMED MATERIALS (E.G. MODULOC - STEEL, PLYWOOD HOARDING, OR SNOW FENCE ON A 2"X4" WOOD FRAME) WITH POSTS 2.4M APART, SUCH THAT THE FENCE LOCATION CANNOT BE ALTERED. ALL SUPPORTS AND BRACING MUST BE PLACED OUTSIDE OF THE

CRZ, AND INSTALLATION MUST MINIMISE DAMAGE TO EXISTING ROOTS.

- 4. THE LOCATION OF THE TREE PROTECTION FENCING MUST BE DETERMINED BY AN ARBORIST AND DETAILED ON ANY ASSOCIATED PLANS FOR THE SITE THE PLAN AND CONSTRUCTED FENCING MUST BE APPROVED BY CITY
- FORESTRY STAFF PRIOR TO THE COMMENCEMENT OF WORK. ARBORIST AND APPROVED BY CITY FORESTRY STAFF. THESE MAY INCLUDE THE PLACEMENT OF PLYWOOD, WOOD CHIPS, OR STEEL PLATING OVER THE ROOTS FOR PROTECTION OR THE PROPER PRUNING AND CARE OF ROOTS WHERE ENCOUNTERED.


THE CITY'S TREE PROTECTION BY-LAW, 2020-340 PROTECTS BOTH CITY-OWNED TREES, CITY-WIDE, AND PRIVATELY-OWNED TREES WITHIN THE URBAN AREA. PLEASE REFER TO WWW.OTTAWA.CA/TREEBYLAW FOR MORE INFORMATION ON HOW THE TREE BY-LAW APPLIES.





















<u>Legend</u>