



Fire Summary and Standard Incident Report (FSSIR)

Incident Type (dispatched to): WORKING FIRE

Address: 6295 FOURTH LINE RD

Cross Street: [None selected]

Incident Begin Time: 12/12/2021 12:17:51

Incident End Time: 12/13/2021 00:45:44

Incident Duration: 12 Hrs 27 Mins 53 Secs

Property Type: 301 Detached Dwelling

Building Name:

OFM Response Type: 01 Fire

Exposure Fire: No

Station Zone: 83

Dispatcher ID: F00085

Alarm to Fire Dept: 01 911

Agent Applied: 12/12/2021 12:34:46

Under Control: 12/12/2021 15:39:03

Area of Origin: Summer Kitchen

Cause: Electrical Failure

Incident Number: 21-89531

Total Staffing: 95

Property Loss: \$750,000

Content Loss: \$0

Exposure Loss: \$0

01/13/2025

Date

Fire Summary and Standard Incident Report (FSSIR)

SECTION A - ALL Emergency Responses

Location Code	Total # Rescues	Total Fire Injuries	Total Fire Fatalities
0608	0	0	0

SECTION B - ALL Fires / Explosions (Response types 01 & 02)

Status On Arrival	7 Fully involved (total structure, vehicle, spreading outdoor fire)		
Water	4 Tanker shuttle service available (no hydrant)		
Fire Control	1 Extinguished by fire department		
Fire Origin (Area)	99 Undetermined		
Igniting Object	999 Undetermined		
Fuel/Energy Igniting Obj	99 Undetermined		
Material First Ignited	99 Undetermined		
Total Loss	\$750,000	Civilian Fire Control	3 Did not attempt to extinguish fire
Estimated Value at Risk	08 \$750,000 to \$999,999	1st Non Evacuation Reason	8 Not applicable - all evacuated or no persons present
		2nd Non Evacuation Reason	

Civilian Actions

Persons Rescued

Children Rescued	0	Child Rescue Condition	98 Not applicable, no persons rescued
Adults Rescued	0	Adult Rescue Condition	99 Undetermined
Seniors Rescued	0	Senior Rescue Condition	98 Not applicable, no persons rescued

Person directly associated with fire ignition

Gender	8 Not applicable	Age	8 Not applicable	Human Factor	06 Unaware of hazard
---------------	------------------	------------	------------------	---------------------	----------------------

SECTION B - Vehicles Only

Vehicle Primary Purpose	Vehicle Fuel Source
--------------------------------	----------------------------

SECTION C - ALL Structure fires or explosions (Response types 01 & 02)

Initial Detection	6 Person detected - visual sighting, smell or sound
Extent of Fire	08 Entire Structure
Smoke Spread	10 Spread beyond building of origin
Est # Persons Displaced	0
Business Impact	8 Not applicable (not a business)
Property Complex	98 Not Applicable
Occupancy Status	01 Permanent - Person(s) Present
Building Status	01 Normal (no change)
Illegal Building Use	8 Not applicable
Building Height	002 2 Storey
Fire Origin (Level)	001 1st Floor
Structure Age	2 Constructed pre 1946 (older)

Smoke Alarms

Alarm on floor or in suite of fire origin

Smoke Alarm on Floor	2 Floor/suite of fire origin: Smoke alarm present and operated
Smoke Alarm Failure Reason	98 Not applicable: Alarm operated, presence/operation undetermined, no alarm
Smoke Alarm Type	1 Battery operated

Alarm on other floor(s)

Smoke Alarm Every Level	1 Yes, Operational alarms on every level
--------------------------------	--

Fire Alarm Systems

Fire Alarm Presence	8 Not applicable for structure type (detached/semi, town residential, other buildings etc)
Fire Alarm Operation	8 Not applicable (no system)
Fire Alarm Impact	8 Not applicable: No fire alarm system, no persons present

Sprinkler System

Sprinkler Presence	3 No sprinkler system present
Sprinkler Operation	8 Not applicable - no sprinkler system present

Fire Summary and Standard Incident Report (FSSIR)

Aeearatus

<u>Aeearatus Name</u>	<u>Diseatch Time/Date</u>	<u>On Scene Time/Date</u>
Air Truck 54	12/12/2021 12:25:55	12/12/2021 13:05:30
Air Truck 548	12/12/2021 12:2036	
All Terrain Vehicle 83	12/12/2021 12:57:21	12/12/2021 12:57:21
All Terrain Vehide 93	12/12/2021 12:38:59	
Brush Truck 83	12/12/2021 12:54 57	12/12/2021 12:56:17
District Chief 40	12/12/2021 12:2615	12/12/2021 12:40:10
Heavy Rescue 82	12/12/2021 12:2036	12/12/2021 12:40:09
INV2	12/12/2021 14:2954	12/12/2021 16:41:53
Ladder47	12/12/2021 12:18:15	12/12/2021 12:32:04
Pumper 37	12/12/2021 12:2036	12/12/2021 12:36:58
Pumper44	12/12/2021 12:2036	12/12/2021 12:39:56
Pumper47	12/12/2021 12:2036	12/12/2021 12:34:05
Pumper82	12/12/2021 12:2036	12/12/2021 12:34:13
Pumper 83	12/12/2021 12:18:15	12/12/2021 12:26:08
Pumper92	12/12/2021 12:18:15	
Pumper92	12/12/2021 12:3623	12/12/2021 12:36:23
Pumper 94	12/12/2021 12:18:15	12/12/2021 12:59:00
Pumper/Tanker 41	12/12/2021 12:2036	12/12/2021 12:47:38
Pumper/Tanker 46	12/12/2021 18:33:37	12/12/2021 18:33:37
Rope Rescue 12	12/12/2021 19:08:17	
Safety Car 23	12/12/2021 12:2036	12/12/2021 12:36:37
Sector Chief 80	12/12/2021 12:18:15	12/12/2021 12:27:15
Sector Chief 80	12/13/2021 00:41 50	
Sector Chief 90	12/12/2021 12:25:17	12/12/2021 12:26:42
Service Vehide 46	12/12/2021 12:2036	12/12/2021 13:08:24
Support Unit 45	12/12/2021 15:0424	12/12/2021 17:16:11
Tanker81A	12/12/2021 12:2203	12/12/2021 12:41:20
Tanker82	12/12/2021 12:2036	12/12/2021 12:34:02
Tanker83	12/12/2021 12:18:15	12/12/2021 12:26:40
Tanker83	12/13/2021 00:3910	
Tanker92	12/12/2021 12:18:15	12/12/2021 12:32:13
Tanker94	12/12/2021 12:18:15	12/12/2021 12:34:10
Tanker94	12/13/2021 00:4201	
Tower37	12/12/2021 12:2036	12/12/2021 12:39:07

Officer's Internal Remarks

Report Date 12/12/2021 16:46:57

Car 80 on location confirmed working fire, century old home two story with summer kitchen and attached garage 100% involved. Winds strong from SW clear sky's 1 degree C
1000ft plus lane way.

Home owner was at home inside. kitchen and notice the lights flicker, went outside and the garage was on fire next to the hydro meter, homeowner went b inside to retrieve two dogs, exited the building and called 911.

P83 attack pump
P47 water supply
P94 water fill.
Car 90 Fire control.
RE82 RIT
P82 Accountability.

Fire Summary and Standard Incident Report (FSSIR)

OPS# 21-320419
Officer Barrett #2603

Car80
Miller.

Officer's Internal Remarks

Report Date 12/12/2021 22:02:22

On arrival ladder 47 staged on the road. Crew went forward and manned hose lines on side 1 later on side 2. Ladder 47 crew performed salvage duties on side 4 and removed numerous items to the exterior.

Officer's Internal Remarks

Report Date 12/14/2021 20:41:55

P83 1st In assume initial IC, updated fully involved 2 story type 5 side 1-and 2 heavy flames and smoke through the roof side 1-2 All clear from resident on scene, 360 started exposures 2 x propane 4001b on side 2 and shed side 2-3. Crews stretch 1 3/4 attack line to side 1-4 corner for suppression and to protect main dwelling, and 2 1/2 long lay to side 2 for suppression and exposure. Transfer IC to C80 assume sector officer once C90 took FC. Continued suppression and salvage and overhaul for duration of the call as required and directed by IC and FC.

Officer's Internal Remarks

Report Date 12/15/2021

- Assisted IC initially as scribe for this call.
- Assisted IC with location of crews and monitoring the radio traffic;
- After some time I was able to leave the Command Post and do a couple 360's to assist in providing IC with a full picture of the incident;
- Worked with Fire Control to develop a plan to quickly perform Salvage operations on Side four; discussed our options on potential exterior operations and fire control.
- Once IC determined that Urban crews were no longer required I was released from scene.

Officer's Internal Remarks

Report Date 12/15/2021 19:47:39

- P44 was parked on 4th Line Rd behind other rigs and walked in long laneway
- Initially tasked with barricading an exclusion zone around an entranceway with low hanging wires
- Removed fence boards to create other openings for crews to use further away from wires
- Assisted exterior crews with defensive handlines, mostly on side 2 and around large propane tanks

Officer's Internal Remarks

Report Date 12/18/2021 09:48:38

P94 - fill site at Kars dock until 1630hrs
TA94 - tanker shuttle
Station 94 - fill site from 1730 to 2130hrs