



Dendron Forestry Services

www.dendronforestry.ca

613.805.WOOD (9663)

info@dendronforestry.ca

Tree Information Report

Submitted as part of Committee of Adjustment Application for the City of Ottawa

Address: 271 Queen Mary

Date: May 19, 2022

Prepared by: Astrid Nielsen, RPF, ISA Certified Arborist ®

Prepared for: Alana Spadaccini, contact at Mike Miroca, mike@mirocadesign.com

Site Visit: May 17, 2022

Committee of Adjustment

Received | Reçu le

2023-08-22

City of Ottawa | Ville d'Ottawa
Comité de dérogation

A site visit revealed that there are no trees protected under City of Ottawa tree by-laws on this property. There are some small Manitoba maple clumps with diameters ranging from 5 to 15 cm along the city laneway in the rear yard that have sprouted from older stumps directly under the hydro lines. The city should consider removing these stems before they become too large or provide authorization to the property owner to remove them without the requirement of a Tree Permit.

The undersigned personally inspected the property and issues associated with this report on May 17, 2022. On Behalf of Dendron Forestry Services,



Astrid Nielsen, MFC, RPF (Registered Professional Forester), ISA Certified Arborist ®, ON-1976

Principal, Dendron Resource Surveys

Astrid.nielsen@dendronforestry.ca

(613) 805-9663 (WOOD)