# CITY OF OTTAWA DEPARTMENT OF PLANNING & DEVELOPMENT COMMUNITY PLANNING BRANCH

# HERITAGE SURVEY AND EVALUATION FORM

BUILDING FILE NO.
PD: 4300 Guigues 73-77
HERITAGE DISTRICT FILE NO.
PD:

Municipal Address: 73-77 Guigues Street

Building Name:

Legal Description:

Date of Construction: 1872-1873 Original Use: Residential - triplex Present Use: Residential - triplex

Present Zoning: HR -1

Planning Area: Lowertown West

Lot PL 10

Block: Guigues N

Plan: 42482

Additions:

Original Owner: unknown

Present Owner: 519121 Ontario Inc.

#### **PHASE ONE SURVEY**

Potential Significance	Considerable	Some	Limited	None
	(Pre- 1878)	( 1878 to 1913	) (1914 to 1957	) ( 1958 to 1992)
History				
(Date of Construction)	3	2	1	0
Architecture	3	2	1	0
Environment	3	2	1	0
(Landmark or Design Co	mpatibility			
	Phase One	Survey Score	/9 Potent	tial Heritage Building Yes/No
	Potential H	eritage District	Yes/No Prepa	red By:



# PHASE TWO EVALUATION RESULTS

(Summarized from Page 4)

Category

1 2

Part V Definite

Yes/No

Part IV Potential

Yes/No

If PART IV, By-law/Date:

IF PART V:

#### HERITAGE DISTRICT NAME:

BY-LAW/DATE:

COMMENTS:

PHOTO DATE: June 1992

VIEW:

SOURCE: Gilberto Prioste NEGATIVE NUMBER:

#### **HISTORY**

PREPARED BY: Michael McClelland

DATE: Summer 1992

Date of Construction: 1872-1873

Factual/Estimated

Sources:

Assessment 1872: Jos. Auchil, tenant; Moise Dupont, freehold; value of real property, 900; in 1871, 800. Assessment 1876: Lincourt, Brunelle and St. Louis, tenants; Dupont, freehold; value, 500 per tenant.

FIPs: shows on all plans with altered rear wings.

City Directories: first listing of triple tenancies, 1872-1873.

#### Trends:

Reflects the development of rental property - replaced a smaller structure - single occupancy.

#### Events: n/a Persons/Institutions:

The early occupants were Mrs. Brumel (1872-73), Mrs. John Keough (later Kehoe, 1872, 1875), and Edouard Brisbois, labourer (1872, 1875), Fabien Gravelle, a labourer (1877, 1878), and Alexis Liancourt (or Lincourt 1875, 1876).

#### Summary/Comments On Historical Significance:

The row reflects typical development patterns from early Lowertown - workers housing which frequent changes in occupancy.

**Historical Sources** 

**ARCHITECTURE** 

PREPARED BY: Michael McClelland

DATE: Summer 1992

Architectural Design (Plan, Storeys, Roof, Windows, Materials, Details, Etc..):

2 storey flat roof row of three houses; angelstone and stucco finish, full width porch executed in metal.

#### **Architectural Style:**

This very altered building with angelstone veneer reveals little of its early appearance. In style it appears to reflect mid-twentieth century design ideas with the angelstone and the metal porch.

#### Designer/Builder/Architect:

unknown.

#### Architectural Integrity (Alterations):

Very altered - "picture windows" on the ground floor; replacement of most finishes. (permit for alterations 1956).

Other (Structure, Interior, Building Type, Etc..):

#### **Summary/Comments On Architectural Significance**:

The vernacular quality of this building can still be appreciated in its use of materials, but it is very altered and does not reflect its earlier appearance.

**ENVIRONMENT** 

PREPARED BY: Michael McClelland

DATE: Summer 1992

Planning Area: Lowertown West

Heritage Conservation District Name (if any):



PHOTO DATE: June 1992 VIEW: SOURCE: Gilberto Prioste NEGATIVE NUMBER:

# **Compatibility With Heritage Environs:**

The building is compatible with others in the area because of its scale, the use of stucco and the presence of a porch, but it is substantially altered.

# Community Context/Landmark Status:

A corner building.

### Summary/Comments On Environmental Significance:

The building only modestly contributes to the character of Lowertown.

# **PHASE TWO EVALUATION**

CRITERIA SCORING												
HISTORY CATEGORY		=====	G	F	P	SCOF	======================================		====			
1. Date of Construction	4	0										
2. Trends			35									
3. Events					0							
4. Persons					0							
HISTORY TOTAL					=====	75 ======						
ARCHITECTURAL CATEGOR		≣	G	F	Р	SCOF	RE					
1. Design				5								
2. Style					0							
3. Designer/Builder					0							
4. Architectural Integrity					0							
ARCHITECTURAL TOTAL						5						
ENVIRONMENT CATEGORY		===== E	G	F	P	SCOF	RE					
1. Design Compatibility			20									
2. Landmark /			20									
Community Context												
ENVIRONMENT TOTAL						40						
Criteria Scoring completed by: EVALUATION COMMITTEE					Date:							
CATEGORY SCORE	DETERMIN IN A POTENTIA					OT IN A POT		RITAGE DIS	TRIC			
History	75	5 x 20%	% = 15			X 4	0% =					
Architecture	5	x 35%	= 1.75	5		X 4	-0% =					
Environment	40	0 x 45%	<b>%</b> = 18			X 2	.0% =					
					75/100 /100							
HERITAGE CLASSIFICA												
Phase Two Total Score	(above	)	(to		) (1	to į	) (Belov	v )				
Group	1		2		3	}	4					
PHASE TWO EVALUATI	ON SUMMARY:	:										

73-77 Guigues St.

Summary Prepared By:

Date: