











East Facade

-  Brick Face Spalling/Broken typical
-  Brick Crushed
-  Brick Repaired
-  Concrete Structural damage







-  Brick Face Spalling/Broken typical
-  Brick Crushed
-  Brick Repaired
-  Concrete Structural damage

West Facade







West Facade





-  Brick Face Spalling/Broken typical
-  Brick Crushed
-  Brick Repaired
-  Concrete Structural damage



West Facade

-  Brick Face Spalling/Broken typical
-  Brick Crushed
-  Brick Repaired
-  Concrete Structural damage



-  Brick Face Spalling/Broken typical
-  Brick Crushed
-  Brick Repaired
-  Concrete Structural damage

West facade